

Title:	TB JBPW-L Pole and Corner Mount Incompatibility	Version:		Date:	010418
Product:	JBPW-L Mount			Page:	1 of 1
Action Required:	None, Information Only				

Summary

The JBPW-L speed dome wall mounting bracket with junction box is incompatible with the PMPL pole mount and the CMPL corner mount. There is no pole mount or corner mount compatible with the JBPW-L bracket at this time. New pole and corner mount brackets are currently being developed for the JBPW-L.

Recommended Options

1. Drill compatible holes into the PMPL or CMPL. The metal is aluminum alloy and soft enough for easy drilling.
2. Replace the JPBW-L with the older JBPW (this item is no longer in the PQG, but is still available). It is compatible with the CMPL and PMPL, but has M20 metric compression glands as opposed to the G3/4 compression fittings on the JPBW-L.
3. Customers who have purchased a JBPW-L can send the JBPW-L back to Hikvision and receive a replacement JBPW at no charge.